



Meena Bazar,  
Uttar pradesh - 262310.  
Mobile No. - 9016063563

**GSTIN -**

**PDI Report No.** VAN00/26/08/A/PA26  
**Name of Transporter** : S.S.NIJAR & SONS  
**Dealer Code** : VAN0000001  
**Vehicle Reg.No.** : 123456  
**PDI Hours** : 2

**Transport GR No.** : 123456  
**Date of Receiving** : 14/08/2025  
**InvoiceNo/Date** : 7270712070 - 14/08/2025  
**Inspected By** : SOHAM KASHYAP

Chassis No.	Engine No.	Tractor Model	FIP No.	Battery No.	Battery Name	Tyre Make/No.			
						Front		Rear	
						LH	APOLLO TYRES/	LH	APOLLO TYRES/
MCG54A3CFJ2200120	GGH6BAA0163	POLARIS RZR	NA	2342	EXIDE	RH	APOLLO TYRES/	RH	APOLLO TYRES/
Sr. No.	Check List Name						Comments		
1	Air cleaner & oil filter						OK		
2	Air cleaner & oil filter						OK		
3	Air cleaner connections						OK		
4	Air cleaner connections						OK		
5	All electrical Switches & Horns						OK		
6	All electrical Switches & Horns						OK		
7	Battery Specific gravity & electrolyte						OK		
8	Battery Specific gravity & electrolyte						OK		
9	Brake pedal free play & brake operation						OK		
10	Brake pedal free play & brake operation						OK		
11	Clutch free play & clutch operation						OK		
12	Clutch free play & clutch operation						OK		
13	Condition of tyres						OK		
14	Condition of tyres						OK		
15	Engine Low/Hi idle RPM						OK		
16	Engine Low/Hi idle RPM						OK		
17	Engine Oil Level						OK		
18	Engine Oil Level						OK		
19	Engine oil pressure at Low/Hi idle RPM						OK		
20	Engine oil pressure at Low/Hi idle RPM						OK		
21	Front wheel alignment						OK		
22	Front wheel alignment						OK		
23	Hydraulic operations						OK		
24	Hydraulic operations						OK		
25	Instruments & guages						OK		
26	Instruments & guages						OK		
27	parking brake working						OK		
28	parking brake working						OK		
29	PTO clutch function (In DC variant)						OK		
30	PTO clutch function (In DC variant)						OK		
31	PTO lever function						OK		
32	PTO lever function						OK		
33	Radiator cap						OK		
34	Radiator cap						OK		
35	Radiator coolant/water level of sub tank						OK		
36	Radiator coolant/water level of sub tank						OK		
37	Road Test						OK		
38	Road Test						OK		
39	Steering oil level						OK		

Sr. No.	Check List Name	Comments
40	Steering oil level	OK
41	Transmission oil level	OK
42	Transmission oil level	OK
43	Water & Oil leakages	OK
44	Water & Oil leakages	OK

Remarks :-

Driver's Name & Signature: kapil

Receiver's Name & Signature

Date: 14/08/2025 Time: 01:21 PM

Created By : Sunil Service