



Mahindra & Mahindra Ltd.

(Farm Equipment Sector, NetFlows360 Division, Phase IV, Industrial Area, S.A.S Nagar, Punjab-16055.)

Meena Bazar,
Uttar pradesh - 262310.
Mobile No. - 9016063563

GSTIN -

Warranty Claims

W / CI No.	: 1001260003	W / CL Date	: 10/06/2025
TaxInvoice No.	: NA	TaxInvoice Date	: NA
NewTaxInvoice No(Partial Rejected Claims)	:	NewTaxInvoice Date	:
Dealer Name	: Vansh ENTERPRISES	AO Name	: N/A
Type of failure	: Regular	DealerCode	: VAN000001

Sr. No. :	: MCG54A3CFJ2200307	EngineSrNo	: GGH6BAA0163
Invoice Date:	: 09/06/2025	Invoice No:	: 7270712070
Customer Name:	: Dheeraj Kumar	Model	: RUBIQ
AWDD Date	: 10/06/2025	Hours	: 300
Operation at the time of failure	: Blower	Job Card No	: VAN00/26/06/A/J6
Dt. Of Complaint	: 10/06/2025	Dt. of Repairs	: 10/06/2025
Customer Phone No	: 7590060652		
Customer's complaint	: LEVELING ROD & LIFT ROD TUBE FAILURES		
Dealer's observation	: GREASING INADEQUATE		
Action Taken / Special Comments	: testing		

Labour

Sr. No.	Labour Code	Description	Lab Amt(Rs.)	Defect Code	Make Code
1	LA002	LABOUR CHARGES	1879.74	AAM	SWR

LR Details

LR NO	Transporter's Name	Receipt Date	LR Date	No of cases	Claim Status
				0	Pending for Approval

Pending for Approval Details

Pending for Approval By	Pending for Approval Name	Pending for Approval Remarks	Pending for Approval Date
NA	NA		NA