



Mahindra & Mahindra Ltd.

(Farm Equipment Sector, NetFlows360 Division, Phase IV, Industrial Area, S.A.S Nagar, Punjab-16055.)

PLOT NO , 28 ,
GANDHINAGAR - .
Mobile No. - 7590050650

GSTIN -

Warranty Claims

W / CI No.	: 1024260006	W / CL Date	: 10/05/2025
TaxInvoice No.	: WA1024260005	TaxInvoice Date	: 10/05/2025
NewTaxInvoice No(Partial Rejected Claims)	:	NewTaxInvoice Date	:
Dealer Name	: KHUSHBU AUTO AGENCY	AO Name	: N/A
Type of failure	: Regular	DealerCode	: KAA382024

Sr. No. :	: MBNZMEBFEGGH00077	EngineSrNo	: GGH6BAA0163
Invoice Date:	: 26/03/2025	Invoice No:	: 7270712070
Customer Name:	: MSDhoni	Model	: Commercial EV
AWDD Date	: 10/05/2025	Hours	: 100
Operation at the time of failure	: Cultivator	Job Card No	: KAA38/26/05/A/J9
Dt. Of Complaint	: 10/05/2025	Dt. of Repairs	: 10/05/2025
Customer Phone No	: 7590060509		
Customer's complaint	: CLUTCH RELEASE BEARING JAM		
Dealer's observation	: CLUTCH FREE PLAY NIL		
Action Taken / Special Comments	: Done		

Labour

Sr. No.	Labour Code	Description	Lab Amt(Rs.)	Defect Code	Make Code
1	SLC111	1R & R Hose Radiator Outlet	12.98	ABD	SUE
2	LMICO	MICO PARTSCHARGES	1879.74	AAK	SSS

LR Details

LR NO	Transporter's Name	Receipt Date	LR Date	No of cases	Claim Status
				0	Approved

Approved Details

Approved By	Approved Name	Approved Remarks	Approved Date
CCM	Deepak_CCM	Approved	10/05/2025