



Mahindra & Mahindra Ltd.

(Farm Equipment Sector, NetFlows360 Division, Phase IV, Industrial Area, S.A.S Nagar, Punjab-16055.)

PLOT NO , 28 ,
GANDHINAGAR - .
Mobile No. - 7590050650

GSTIN -

Warranty Claims

W / CI No.	: 1024260008	W / CL Date	: 11/05/2025
TaxInvoice No.	: NA	TaxInvoice Date	: NA
NewTaxInvoice No(Partial Rejected Claims)	:	NewTaxInvoice Date	:
Dealer Name	: KHUSHBU AUTO AGENCY	AO Name	: N/A
Type of failure	: Regular	DealerCode	: KAA382024

Sr. No. :	: MBNZMEBFEGGH00073	EngineSrNo	: GGH6BAA0163
Invoice Date:	: 26/03/2025	Invoice No:	: 7270712070
Customer Name:	: Rohit Sharma	Model	: Commercial EV
AWDD Date	: 08/05/2025	Hours	: 301
Operation at the time of failure	:	Job Card No	: KAA38/26/05/A/J8
Dt. Of Complaint	: 10/05/2025	Dt. of Repairs	: 10/05/2025
Customer Phone No	: 7590060504		
Customer's complaint	: CLUTCH OPERATION HARD		
Dealer's observation	: FINGERS HEIGHT INCREASED		
Action Taken / Special Comments	: done		

Parts Details

Sr. No.	Part No.	Part Desc.	Qty	Amount(Rs.)	Make Code	Defect Code	FOC
1	001082012R2	AA_Seat	1	123.90	SWR	AAL	No

Labour

Sr. No.	Labour Code	Description	Lab Amt(Rs.)	Defect Code	Make Code
1	SLC111	1R & R Hose Radiator Outlet	12.98	AAL	SWR
2	LA002	LABOUR CHARGES	1879.74	AAH	SWR

LR Details

LR NO	Transporter's Name	Receipt Date	LR Date	No of cases	Claim Status
				0	Pending for Approval

Pending for Approval Details

Pending for Approval By	Pending for Approval Name	Pending for Approval Remarks	Pending for Approval Date
NA	NA		NA